

References

- Adelman, 1994.** Adelman, A. A. 1994. *Lessons Learned from the Northridge Earthquake*. Hearing before the United States House of Representatives Committee on Science, Space, and Technology, March 2, 1994. Washington, DC.
- Angell et al., 1994.** Angell, M., et al. 1994. "Post-Earthquake Geologic Investigations of the January 17, 1994, Northridge Mw6.7 Earthquake, Northern San Fernando and Santa Clarita Valleys, California." *Program for Northridge Abstracts*. Seismological Society of America, annual meeting, 1994. El Cerrito, CA: SSA.
- Astaneh-Asl et al., 1994.** Astaneh-Asl, A., et al. 1994. *Seismic Performance of Steel Bridges During the 1994 Northridge Earthquake*. Report to California Department of Transportation, UCB/CE-Steel-94/01, April 1994. Berkeley, CA: Department of Civil Engineering, University of California.
- ATC, 1978.** Applied Technology Council. 1978. *Tentative Provisions for the Development of Seismic Regulations for Buildings*. ATC 3-06 (second printing 1984). Palo Alto, CA: ATC.
- ATC, 1989.** Applied Technology Council. 1989. *Procedures for Post Earthquake Safety Evaluation of Buildings*. ATC-20. Redwood City, CA: ATC.
- Barnhart and Slosson, 1973.** Barnhart, J. T., and J. E. Slosson. 1973. "Northridge Hills and Associated Faults—A Zone of High Seismic Probability." *Geology, Seismicity, and Environmental Impact*. Special Publication. Association of Engineering Geologists.
- Bocchicchio, 1994.** Bocchicchio, M. 1994. *Capital Program Data Sheets Detailing Northridge Damage at the UCLA Campus*. Los Angeles, CA: UCLA.
- Brooks, 1994.** Brooks, H. 1994. Tilt-ups and Earthquakes: A Post-Northridge Assessment. Unpublished paper.
- CDMG, 1994.** California Division of Mines and Geology. 1994. *Third Quick Report on CSMIP Strong-Motion Data from the Northridge/San Fernando Valley Earthquake of January 17, 1994*. Sacramento, CA: CDMG.
- Chang, 1994b.** Chang, J. C. 1994. "Review Comments on Bridge Background Report." *Compendium of Background Reports on the Northridge Earthquake for Executive Order W-78-94*. SSC 94-08. Sacramento, CA: SSC.
- Cheu, 1994.** Cheu, D. 1994. *Northridge Earthquake—January 17, 1994: The Hospital Response*. SSC 94-11. Sacramento, CA: SSC.
- Comerio, 1995.** Comerio, M. C., with Hamilton Rabinovitz Alschuler, Inc. 1995. *The Northridge Earthquake Housing Losses*. A report to the California Governor's Office of Emergency Services. Prepublication draft. Berkeley, CA: Center for Environmental Design Research, University of California.
- CSUCCP, 1993.** California State University Committee on Campus Planning. 1993. "Buildings and Grounds." *California State University Policy on Seismic Safety*. May 19, 1993. Sacramento, CA: CSU.
- DSA, 1994b.** Division of the State Architect, Office of Regulation Services. 1994. *Northridge Earthquake—Public School Buildings*. Sacramento, CA: DSA.
- DSA/OES, 1990.** Division of the State Architect and Office of Emergency Services. 1990. *Identification and Reduction of Nonstructural Earthquake Hazards in California Schools*. Sacramento, CA: DSA.
- EERC, 1994c.** Earthquake Engineering Research Center; J. P. Moehle, ed. 1994. *Preliminary Report on the Seismological and Engineering Aspects of the January 17, 1994, Northridge Earthquake*. Report UCB/EERC-94/01. Berkeley: University of California.
- EERI, 1994b.** Earthquake Engineering Research Institute; J. F. Hall, ed. 1994. *Northridge Earthquake January 17, 1994, Preliminary Reconnaissance Report*. El Cerrito, CA: EERI.
- EERI, 1994c.** Earthquake Engineering Research Institute, Ad Hoc Committee on Seismic Performance. 1994. "Expected Seismic Performance of Buildings." *Spectra*. February 1994. El Cerrito, CA: EERI.
- Hamburger and McCormick, 1994a.** Hamburger, R., and D. McCormick. 1994. "Implications of the January 17, 1994, Northridge Earthquake on Tilt-up and Masonry Buildings with Wood Roofs." *Structural Engineers Association of Northern California, May 17 and 18, 1994, Seminar Papers*. San Francisco, CA: SEAONC.
- Hamburger and McCormick, 1994b.** Hamburger, R., and D. McCormick. 1994. "Lessons Learned in the Northridge Earthquake on Wood Frame Buildings." *Structural Engineers Association of Northern California, May 17 and 18, 1994, Seminar Papers*. San Francisco, CA: SEAONC.

- Harthorn, 1992.** Harthorn, R. W. 1992. An untitled, unpublished project for the Masters of Public Administration Class Number 512A, "Intergovernmental Relations," Professor M. Sedell, instructor, California State University, Northridge.
- Housner, 1994.** Housner, G. W.; C. C. Thiel, ed. 1994. *Continuing Challenge: The Northridge Earthquake of January 17, 1994: Report to the Director, California Department of Transportation, by the Seismic Advisory Board.* Sacramento, CA: Caltrans.
- King, 1994.** King, E. (chief of Housing Standards, Department of Housing and Community Development). 1994. Letter to L. Thomas Tobin, executive director, Seismic Safety Commission, dated June 23, 1994.
- LA Times, 1994.** *Los Angeles Times.* January 20, 1994.
- LAFD, 1994.** Los Angeles Fire Department. 1994. *Damage Assessment Overview of the Northridge Earthquake—January 17, 1994.* February 1994. Los Angeles: LAFD.
- LAFD/EMS, 1994.** Los Angeles Fire Department and Emergency Medical Systems. 1994. "EMS Response." *Industrial Emergency Council Conference: Los Angeles Earthquake—What Can We Learn?*; J. Denney ed. San Carlos, CA: IEC.
- LAHD, 1994.** Los Angeles Housing Department. 1994. *Northridge Earthquake of January 17, 1994: First Anniversary Report.* Los Angeles, CA: LAHD.
- McClure, 1984.** McClure, F. 1984. "Development and Implementation of the University of California Seismic Safety Policy." *Proceedings of the Eighth World Conference on Earthquake Engineering.* Vol. 7. Englewood Cliffs, NJ: Prentice-Hall.
- McGavin, 1994.** McGavin, G. 1994. *Observations of Public Educational Facilities Within the Epicentral Area of the January 17, 1994, Northridge, CA, Earthquake.* Ontario, CA: HMC Group.
- McGavin and Patrucco, 1994.** McGavin, G., and H. Patrucco. 1994. "Survey of Non Structural Damage to Healthcare Facilities in the January 17, 1994, Northridge Earthquake." Ontario, CA: HMC Group.
- Murray, 1994.** Murray, J. 1994. *Performance of Health Care Facilities During the Northridge Earthquake; Damage to Water Lines and Failure of Emergency Generators.* June 10, 1994. Sacramento, CA. OSHPD.
- NCSBCS, 1994.** National Conference of States on Building Codes and Standards, Inc. 1994. *Northridge Earthquake Effects on Manufactured Housing in California.* Washington, DC: Housing and Urban Development Department.
- NOAA/EERI, 1973.** NOAA/EERI Earthquake Investigation Committee, Subcommittee on Buildings; L. M. Murphy, ed. 1973. "Wood Roof and Masonry Wall Buildings—Summary, Conclusions and Recommendations." *San Fernando, California, Earthquake of February 9, 1971: Effects on Building Structures.* 1:127-128. Washington, DC: NOAA.
- O'Rourke and Palmer, 1994.** O'Rourke, T. D., and M. C. Palmer. 1994. *Replacement Procedures and Earthquake Performance of Gas Transmission Pipelines.* Prepared for the Southern California Gas Company and the National Center for Earthquake Engineering Research. Ithaca, NY: School of Civil and Environmental Engineering, Cornell University.
- OSHPD, 1994a.** Office of Statewide Health Planning and Development. 1994. *Report to the Building Safety Board on the Performance of Hospital Buildings in the Northridge Earthquake of January 17, 1994.* Sacramento, CA: OSHPD.
- OSHPD, 1994b.** Office of Statewide Health Planning and Development. 1994. "Weekly Damage Report Summary, Monday, March 7, 1994." Sacramento, CA: OSHPD.
- OTA, 1990.** U.S. Congress, Office of Technology Assessment. 1990. *Physical Vulnerability of Electric Systems to Natural Disasters and Sabotage.* OTA-E-453. Washington, DC: Government Printing Office.
- Palo Alto, 1991.** City of Palo Alto. 1991. *Ordinance 4090, Adopting the 1991 Editions of the Uniform Building Code and the Uniform Mechanical Code.* Section 16.04.025, Exception 2. Palo Alto, CA: Palo Alto.
- Pearson et al., 1993.** Pearson, J., et al. 1993. *Full-Scale Laboratory Testing of Manufactured Housing Lateral Load Restraint Devices for U.S. Department of Housing and Urban Development.* HUD-006360. Northbrook, IL: Wiss, Janney, Elstner Associates, Inc.
- Pickett, 1994.** Pickett, M. A. 1994. *17 January 1994 Northridge Earthquake.* Toledo, OH: University of Toledo Dept. of Civil Engineering.
- Romero, 1994.** Romero, P., Ph.D. 1994. Testimony before the Seismic Safety Commission.
- Schierle, 1993.** Schierle, G. G. 1993. *Quality Control in Seismic Resistant Construction.* Report to the National Science Foundation on research under Grant BCS-9203339. Los Angeles, CA: NSF.

- Schmid, 1994b.** Schmid, B. 1994. "Report of Field Observation of Unreinforced Masonry Buildings in Area Most Affected by the 1/17/94 Northridge Earthquake." Letter to Department of Building & Safety—Los Angeles, January 29, 1994.
- SEAOC, 1990.** Structural Engineers Association of California. 1990. "Recommended Lateral Force Requirements and Commentary." *SEAOC Blue Book*. Sacramento, CA: SEAOC.
- Shakal et al., 1994.** Shakal, A., et al. 1994. *CSMIP Strong Motion Records from the Northridge, CA, Earthquake of January 17, 1994*. Report OSMS 94-07. Sacramento, CA: CDMG.
- Slosson, 1994.** Slosson, J. E. 1994. "Geosciences Observations, Statements, and Recommendations Related to the January 17, 1994, Northridge Earthquake." Memo dated May 16, 1994, to the Seismic Safety Commission.
- Snyder, 1994.** Snyder, Pat. 1994. "Emergency Medical Response Following the Northridge Earthquake." *Compendium of Northridge Earthquake Issue Papers by the Seismic Safety Commissioners*. Sacramento, CA: SSC.
- SSC, 1990.** Seismic Safety Commission. 1990. *Report to the Governor on Executive Order D-86-90*. SSC 90-06. Sacramento, CA: SSC.
- SSC, 1992a.** Seismic Safety Commission. 1992. *Homeowner's Guide to Earthquake Safety*. SSC 92-02. Sacramento, CA: SSC.
- SSC, 1992b.** Seismic Safety Commission. 1992. *Right to Know: Disclosure of Seismic Hazards in Buildings*. SSC 92-03. Sacramento, CA: SSC.
- SSC, 1994a.** Seismic Safety Commission. 1994. *Compendium of Background Reports on the Northridge Earthquake for Executive Order W-78-94*. SSC 94-08. Sacramento, CA: SSC.
- SSC, 1994f.** Seismic Safety Commission. 1994. *Research and Implementation Plan for Earthquake Risk Reduction in California*. SSC 94-10. Sacramento, CA: SSC.
- SSC, 1994g.** Seismic Safety Commission. 1994. "Steel Moment Resisting Frame Buildings—Status Report." Advisory memo of November 17, 1994. Sacramento, CA: SSC.
- USGS, 1994a.** U.S. Geological Survey. 1994. "Ground Deformation in Granada Hills from the January 17, 1994, Northridge Earthquake." *Program for Northridge Abstracts*. Seismological Society of America, annual meeting, 1994. El Cerrito, CA: SSA.
- USGS, 1994b.** U.S. Geological Survey. 1994. "Ground Deformation in Potrero Canyon from the January 17, 1994, Northridge Earthquake." *Program for Northridge Abstracts*. Seismological Society of America, annual meeting, 1994. El Cerrito, CA: SSA.

